



Government of Karnataka
(Public works Department)
No.3 subdivision, Karkala-574104.
Telephone & Fax no.(08258) 230202.
E-mail : aepwdkkl@gmail.com

No :PWD/BLD/SCHOOL/2021-22/JE/ 278 /Date:19.06.2021

TO,

President,
S.R. Education Trust (R.),
Kinnigudde,
Hebri Taluk,
Udupi District.

Sir,

Sub: Issue of 'Building Safety Certificate' to S R Public School building,
situated at Hebri bearing Survey No. 11/1P of Hebri village,
Hebri Taluk, Udupi District.

Reff.No.:

1. No.185/FSR/CFO/MD/2021, 'Fire Safety Compliance Certificate' issued by the office the Chief Fire Officer Karnataka State Fire and Emergency Services Mangalore
2. SMVITM/TCC/2021-22/40, 'Building Stability Report' inspected and reported by Department of Civil Engineering Shri MadhwaVadiraja Institute of Technology and Management, Bhantakal – 574 115
3. 25/2020-21, letter dated: 18/06/2021 from Principal, S R Public School, KinniguddeHebri -576 112

* * * *

With reference no. 1 the chief Fire Officer and team inspected school about fire safety for the students on 08/06/2021. After inspection and observing proper installation of fire fighting instruments in good working conditions the Chief Fire Officer Karnataka State Fire and Emergency Services Mangalore issued the "Fire Safety Compliance Certificate" for S R Public School, KinniguddeHebri – 576 112.

With reference no.2 the Nodal Officer and team of Testing and consultancy Cell, Department of Civil Engineering, Shri MadhwaVadiraja Institute of Technology and Management, Bhantakal inspected the school on 17/06/2021 by visual observation, oral enquires and rebound hammer testing, given 'Building Stability Report' about general health of the structural system of the building for S R Public School, KinniguddeHebri, Hebri Taluk, Udupi District.

Under the above circumstances Inspected the site of the school bearing survey no. 11/1P of Hebri village, Hebri Taluk and Udupi District on 19/06/2021, observed building conditions good maintain, therefore We certify that the general health of the building system is good. Hence the building is structurally safe and fit for occupancy. This certificated valid for 10 years from issue date.

Your's faithfully,

Assistant Executive Engineer,
Public Works Department,
No.3 Subdivision, Karkala